Engineering Report

Wakefield Security Systems Limited Unit 8 Water Lane Storrington West Sussex RH20 3DW 01903 823033



Administration@wakefield-security.uk

Site Name Dove (Littlehampton) Ltd Address 49 Beach Road Littlehampton West Sussex

BN17 5JG

49 Beach Road Littlehampton West Sussex

Dove(Littlehampton) Ltd

BN17 5JG

Site ID 002107

Contact Mr Mike Clayden Customer Reference

- System Type Fire Detection and Alarm System BS5839 Pt 1 (002894)
- Call No. 12678 Type Preventative Maintenance Reason Preventative Maintenance

Description AM CALL (10/11/23) Confirmed with Mike via telephone 12/10/23- no problems to report

Directions: HKC app 289314 Call Remarks: 7amp Battery replaced 17/5/19 Preventative Maintenance : Fire Equipment Annual Visit Notes :

Started 10/11/23 @ 12:23:00 Finished 10/11/23 @ 13:38:00

Remarks Routine maintenance visit checked and tested system all ok.

All tested, excluding lift shaft and boiler room heat detector as tested last visit.

All tested ok no faults found.

Relay not tested as Mike not on site today !

Checklist

Check Item	<u>Checked ?</u>	<u>Remarks</u>
Check with users that there have been no other problems since last visit	Yes	
Check for changes in the building since the last visit, and the system conforms to the Fire Grading	No	unknown fire grading requirements
Check the satisfactory operation of all detection devices including deliberately operated devices	Yes	
Inspect all flexible connections	Yes	
Inspect exposed wiring for damage, if applicable	Yes	
Check all batteries with discharge meter (replace if older than 4 years)	Yes	Checked and tested
Carry out System Performance Checks to record battery voltages and charging currents		
Control panel. Check mains and standby power	Yes	Checked and tested

supply, including correct charging rates.	
Check control unit for correct operation	Yes
Check the operation of any automatic remote signalling or receiving equipment	No
Test remote signalling equipment through to ARC	No
Check all audible warning and alarm devices for correct operation (Min 65db or 75db at bed heads)	Yes
Check all egress points including Access Controlled doors "fail unlocked" if specified to do so	Yes
Check all manual call points for correct operation	Yes
Record below the detectors checked during this visit (If over manufacturers recommended life they must be replaced).	Yes
Are there any discrepancies between the specification and the installed equipment?	No

na na

> Checked and tested everything excluding lift shaft and boiler room heat as both tested last visit.

no specification available

Engineer Signature

UM

Customer Signature

Hame

Engineer

Andy Vicarage

Name

NA