

Service Attendance Form

Site Details

MNumber:	M31898	Site Contact:	Mike
Site Name:	Dove Lodge	Contract Type:	BRONZE
Site Address:	49 Beach Road	Engineer:	0390
Site Postcode:	BN17 5JG	Route No:	57
Customer Lift Ref:	HPL Passenger Lift	Supervisor:	Rob Loder
Property Code:			

Service Work Details

Visit Month:	June	Date:	07/08/23
Main Ropes/Chains:	N/A	Tank Unit/Pipes:	Worn but Serviceable
Wiring/Flexes:	Worn but Serviceable	Rupture Valve/Safety Rope	Worn but Serviceable
Doors/Operator:	Worn but Serviceable	Controller:	Worn but Serviceable
Ram/Ram Seal:	Worn but Serviceable		
Service Type:	The service inspection type undertaken during this visit was type Z - Items visually checked during this visit may include (but are not limited to), controller, motors/generators, main sheave, winding gear, brake unit, car entrances, door/gate operators, safety gear/guides, lift alarm, landing entrances, landing protection, and shaft equipment. For a full break down of this service plan, please check your Jackson Lift Service Plan & Method Statement.		

Other Work Completed this Visit

Safety Test:	An annual JLG Safety Test is not included as a part of your contract. If you would like a test to be carried out please contact your supervisor rloder@jacksonlifts.com .		
Fire Control Switch:	Is a manually operated fire safety switch fitted?		No
	When activated does the lift function as designed?		N/A
Fire Alarm Return/Recall:	Is a fire alarm return/recall facility fitted?		No
	Is the facility Manual or Automatic/BMS?		N/A
	When the manual system is activated does the lift function as designed?		N/A

Autodialler	Installed	Audible Alarm Functional	Line Functional	Calls JLG helpdesk
Test Results:	Yes	Yes	Yes	Yes

Comments

General Remarks

- All Due Health & Safety, LG Examinations Will Be Quoted When And As Appropriate
- Rec Doo Detector Edges Fitted, No Car Top Emergency Light, No Low Level Pit Stop
- Switch.Notice In Pit Informing Ladder Is In M/room.M/room Socket Not RCD Type.
- No Car Emergency Light, None Lift Materials In M/room. No Pit Prop Notice.
- *Above Reported On Engineer 1st Service Visit*

Sign Off

Engineer Name:	Graeme Norris	Client Name:	
Signature:		Signature:	

